

Work Order ID 57691

April 13, 2010 2:49:02 PM

Page 1

Item ID: D2914-142

Accept

Revision ID:

Item Name: 3" Outer Tube

Start Date: 4/13/10

Start Qty: 2.00

Required Date: 4/14/10

Req'd Qty: 2.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

QC:

Date:

SPC (Y/N):

Date:

Run

Start

Stop

Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Draw  
Number

Draw  
Rev.

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr

Revision Nbr

D2914

Rev A1

135

0.00



Skidtubes

Memo

0.00

Skidtubes

PULL FROM STOCK:

2 X D2914-142 B12228

SCRAP/DESTROY- PARTS ARE DENTED

Q.7 10 - 04 - 27 @

140

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/04/30

W 1206.29

# Picklist Print

April 13, 2010 2:49:01 PM

Work Order ID: 57691



Parent Item: D2914-142



Parent Item Name: 3" Outer Tube

Start Date: 4/13/10

Required Date: 4/14/10

Comments: IPP D02.09.05 Added DSK 066 KJ

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2914-142		Manufactured	No				Each	79.0000	2.0000			



3" Outer Tube



Warehouse

Loc Qty

Loc Code

Location

Main Warehouse

HALL

14092

79

79

*DP*

*10-4-28*

*2*